




TORQUE RODS

TORQUE RODS

The TRP All Makes Torque Rods are designed to meet industry standards and survive any harsh road conditions. TRP Torque Rod assemblies are manufactured utilizing advanced materials, forms, construction and fastening methods and incorporate multiple technologies to prevent “walk out” of the bushing.



FEATURES & BENEFITS

- » Offers a broad range of sizes to cover popular applications
- » Lighter than conventional construction maximizing durability and quality
- » 1 year no-hassle warranty
- » Bonded and Curl & Bonded options

| TRP | OEM | OEM CROSS | ATRO | AUTOMANN | TENNECO/ CLEVITE |
|------------|------------------------------------|---|---------------|----------|--|
| TQRAA1-410 | FREIGHTLINER | 16-19351-000, 16-16141-000 | | | |
| TQRAA1-423 | FREIGHTLINER | 16-19505-000, 16-19567-000 | | TMR516F | TR010010070 |
| TQRAA1-605 | FREIGHTLINER | 16-15632-001, 16-18972-001, 16-16749-001 | TR46-41716ATR | TMR534 | TR030010030 |
| TQRAA1-615 | FREIGHTLINER, NAVISTAR | 16-18972-000, 16-16749-002, 16-15632-000, ATRTR4641000 | TR46-41000ATR | TMR536 | TR030010040 |
| TQRAA1-645 | NAVISTAR | 16405001 | TR55-428C1ATR | TMR533 | FS28A939710N |
| TQRAA1-649 | PACCAR | C65-6025-000000649, C65-6020, C65-6028-000000649 | TR00-41009ATR | TMR553 | TR030020010, TR010300021, TR010030131, FS28A923230K, TT44A937530AA, 937530 |
| TQRAA1-737 | NAVISTAR, VOLVO/MACK | 1661935C92, 5435-644600 | TR00-41935ATR | TMR693 | 925600 |
| TQRAA2-440 | PACCAR | C65-6026-000010440 | TR75-41327ATR | TMR549 | TR020420010, 947790 |
| TQRAA2-460 | NAVISTAR | 3581271C1 | TR55-41117ATR | TMR508 | 947104 |
| TQRAA2-581 | PACCAR | C65-6027-000000581 | TR50-42580ATR | TMR551 | TR010021560 |
| TQRAA2-603 | NAVISTAR, VOLVO/MACK | 1516350C92, 17QF457P238 | TR62-41238ATR | TMR574 | |
| TQRAA2-610 | FREIGHTLINER, NAVISTAR, VOLVO/MACK | 6813262065, 1661925C92, 17QF460P240, 1RY39307P13, 25164946, 5435-947794 | TR59-41375ATR | TMR67 | FS32A925030, 944270 |
| TQRAA2-645 | NAVISTAR | 3548381C1 | TR55-418C1ATR | TMR533 | TR010020060 |
| TQRAA2-649 | PACCAR | C65-6027-000000649 | TR75-41108ATR | TMR532 | TR010021550 |
| TQRAB1-587 | PACCAR | C65-6029-000587 | TR50-41587ATR | TMR674 | FS320110070K, 924901 |
| TQRAB1-610 | PACCAR, VOLVO/MACK | C65-6029-000610, 17QF455P240 | TR59-41376ATR | TMR69 | FS32A972158AAK, FS32A925031, TR020020050, FS321070010, 925031, 972158 |
| TQRAB2-638 | FREIGHTLINER | 6813267016 | TR59-41150ATR | TMR514 | FS32A925161BBD |
| TQRAC1-604 | PACCAR | C65-6023-001 | TR00-41001ATR | TMR537 | TR010040030, 937560 |
| TQRAC1-605 | PACCAR | C65-6023-003 | | | TR010040050 |
| TQRAC1-627 | PACCAR | C65-6023-002 | TR00-41600ATR | TMR539 | TR010040040, 937561 |
| TQRAC1-637 | PACCAR | C65-6023-004 | | | TR010040060 |